



Photo 1: Griggstown Lock upstream side.



Photo 2: Griggstown Lock downstream side.



Electric lines may need to be temporarily relocated during work

03/03/2022

Photo 3: 10 Mile Lock upstream side.



03/03/2022

Photo 4: 10 Mile Lock downstream side.





Photo 5: South Bound Brook upstream side.



Photo 6: South Bound Brook lock left sluice gate work area dewatered.





Photo 7: South Bound Brook downstream side.



Photo 8: 5 Mile Lock upstream side.



Photo 9: 5 Mile Lock downstream side.